OPTIMUS AUTO TRADING GROUP

REPORT DATE
Fri Nov 06 2026
REPORT VERSION: 6

Vehicle Inspection Report

Stock No.: OAT-R1R7AN

VEHICLE SPECIFICATIONS

Stock No.	OAT-R1R7AN	**Chassis Number**	WDF44760323040901
Engine Size	1598 cc	**Transmission**	MANUAL
Mileage	220,400 km	**Registration Date**	2016-03-28
Make and Model	Mercedes-Benz VITO 109 CDI MT LONG	**Exterior Colour**	WHITE
Propellant	DIESEL	**Seats**	3
Dimensions	5.25 × 1.91 m		


STANDARD FEATURES

✓ Driver Airbag	✓ Power Steering	✓ Power Mirrors
✓ Leather Seats	✓ Fog Lights	✓ Central Locking System
✓ Electronic Stability Control (ESC)	✓ Non-Smoker	✓ Air Conditioning
✓ Antilock Braking System (ABS)	✓ AM/FM Radio	✓ Alloy Wheels
✓ Power Windows	✓ Passenger Airbag	

SUPPLIER'S CONDITION REPORT

Corrosion	✓ No	Yes	
Under Body Holes	✓ No	Yes	
Under Body Broken	✓ No	Yes	
Engine	✓ Working	Not Working	None
Brake System	✓ Working	Not Working	None
Power Window	✓ Working	Not Working	None
Transmission	✓ Working	Not Working	None
A/C	✓ Working	Not Working	None
Audio System	✓ Working	Not Working	None
4WD	Working	Not Working	✓ None

BODY CONDITION



LEGEND

A	**Minor Dent** Approx. 20-cent coin size
B	**Major Dent** Approx. $1 coin size

BODY CONDITION DETAILS

No.	Defect	Information Details
F1	Other	Minor scratch (Rigt side mirror)
F2	Other	Minor scratch (Left side headlamp)
F3	Other	Minor scratch (Front hood)

No.	Defect	Information Details
F4	Other	Loose bumper (Rear left bumper)

Date: 11/6/2026

Optimus Auto Trading Group

This report is generated for internal use and customer reference. All information is accurate as of the date of inspection. Any subsequent alterations, adjustments or events are not covered in this evaluation.