

Vehicle Inspection Report

Stock No.: OAT-K6H1VP

VEHICLE SPECIFICATIONS

Stock No.	OAT-K6H1VP	Chassis Number	JTHBH1D2905104149
Engine Size	2494 cc	Transmission	Automatic
Mileage	9 km	Registration Date	2025
Make and Model	LEXUS IS300H 300h EXECUTIVE	Exterior Colour	WHITE
Propellant	HYBRID(Petrol)	Seats	5
Dimensions	4.71 × 1.84 m		


STANDARD FEATURES

✓ Keyless Entry	✓ Passenger Airbag	✓ Power Windows
✓ Power Seat	✓ Back Camera	✓ Alloy Wheels
✓ AM/FM Radio	✓ Antilock Braking System (ABS)	✓ Air Conditioning
✓ Non-Smoker	✓ Electronic Stability Control (ESC)	✓ Central Locking System
✓ 360-Degree Camera	✓ Push Start	✓ Power Steering
✓ Power Mirrors	✓ Leather Seats	✓ Driver Airbag
✓ Navigation		

SUPPLIER'S CONDITION REPORT

Corrosion		Yes	
Under Body Holes		Yes	
Under Body Broken		Yes	
Engine		Not Working	None
Brake System		Not Working	None
Power Window		Not Working	None
Transmission		Not Working	None
A/C		Not Working	None
Audio System		Not Working	None
4WD	Working	Not Working	

BODY CONDITION



LEGEND

- A** Minor Dent
Approx. 20-cent coin size
- B** Major Dent
Approx. \$1 coin size

BODY CONDITION DETAILS

No body-condition defects have been recorded for this vehicle.

Date: 9/24/2026

Optimus Auto Trading Group

This report is generated for internal use and customer reference. All information is accurate as of the date of inspection. Any subsequent alterations, adjustments or events are not covered in this evaluation.