OPTIMUS AUTO TRADING GROUP

REPORT DATE
**Tue Nov 17 2026**
REPORT VERSION: 2

# Vehicle Inspection Report

Stock No.: OAT-6G2GPE

## VEHICLE SPECIFICATIONS

| | | | |
|---|---|---|---|
| **Stock No.** | OAT-6G2GPE | **Chassis Number** | WBAHS120105F02874 |
| **Engine Size** | 1499 cc | **Transmission** | Automatic |
| **Mileage** | 63,000 km | **Registration Date** | 2016-11-16 |
| **Make and Model** | BMW X1 SDRIVE18I AT LED NAV | **Exterior Colour** | GRAY / GREY |
| **Propellant** | PETROL / GASOLINE | **Seats** | 5 |
| **Dimensions** | 4.45 × 1.82 m | | |


## STANDARD FEATURES

| | | |
|---|---|---|
| ✓ Keyless Entry | ✓ Passenger Airbag | ✓ Power Windows |
| ✓ Power Seat | ✓ Back Camera | ✓ Alloy Wheels |
| ✓ AM/FM Radio | ✓ Antilock Braking System (ABS) | ✓ Non-Smoker |
| ✓ Electronic Stability Control (ESC) | ✓ Central Locking System | ✓ Navigation |
| ✓ Fog Lights | ✓ Leather Seats | ✓ Power Mirrors |
| ✓ Driver Airbag | ✓ Power Steering | ✓ Push Start |

## SUPPLIER'S CONDITION REPORT

| | | | |
|---|---|---|---|
| **Corrosion** | ✓ No | Yes | |
| **Under Body Holes** | ✓ No | Yes | |
| **Under Body Broken** | ✓ No | Yes | |
| **Engine** | ✓ Working | Not Working | None |
| **Brake System** | ✓ Working | Not Working | None |
| **Power Window** | ✓ Working | Not Working | None |
| **Transmission** | ✓ Working | Not Working | None |
| **A/C** | ✓ Working | Not Working | None |
| **Audio System** | ✓ Working | Not Working | None |
| **4WD** | Working | Not Working | ✓ None |

## BODY CONDITION




## LEGEND

| | |
|---|---|
| A | **Minor Dent**<br>Approx. 20-cent coin size |
| B | **Major Dent**<br>Approx. $1 coin size |

## BODY CONDITION DETAILS

| No. | Defect | Information Details |
|---|---|---|
| F1 | Other | Minor scratch (Right rear door) |

**Date: 11/17/2026**

This report is generated for internal use and customer reference. All information is accurate as of the date of inspection. Any subsequent alterations, adjustments or events are not covered in this evaluation.