

Vehicle Inspection Report

Stock No.: OAT-GRDL5X

VEHICLE SPECIFICATIONS

Stock No.	OAT-GRDL5X	Chassis Number	WBA5A52000G390079
Engine Size	1997 cc	Transmission	Automatic
Mileage	77,000 km	Registration Date	2016-04-18
Make and Model	BMW 5 SERIES 528I AT D/AB LED NAV REV/CAM	Exterior Colour	Blue
Propellant	PETROL / GASOLINE	Seats	5
Dimensions	5.00 × 1.90 m		


STANDARD FEATURES

✓ Keyless Entry	✓ Power Windows	✓ Passenger Airbag
✓ Power Seat	✓ Back Camera	✓ Alloy Wheels
✓ AM/FM Radio	✓ Push Start	✓ Driver Airbag
✓ Power Mirrors	✓ Power Steering	✓ Leather Seats
✓ Side Airbags	✓ Navigation	✓ Antilock Braking System (ABS)
✓ Air Conditioning	✓ Electronic Stability Control (ESC)	✓ Non-Smoker
✓ Central Locking System		

SUPPLIER'S CONDITION REPORT

Corrosion	No	Yes	
Under Body Holes	No	Yes	
Under Body Broken	No	Yes	
Engine	Working	Not Working	None
Brake System	Working	Not Working	None
Power Window	Working	Not Working	None
Transmission	Working	Not Working	None
A/C	Working	Not Working	None
Audio System	Working	Not Working	None
4WD	Working	Not Working	None

BODY CONDITION



LEGEND

- A** Minor Dent
Approx. 20-cent coin size
- B** Major Dent
Approx. \$1 coin size

BODY CONDITION DETAILS

No body-condition defects have been recorded for this vehicle.

Date: 9/22/2026

Optimus Auto Trading Group

This report is generated for internal use and customer reference. All information is accurate as of the date of inspection. Any subsequent alterations, adjustments or events are not covered in this evaluation.