

Vehicle Inspection Report

Stock No.: OAT-SXCZ00

VEHICLE SPECIFICATIONS

Stock No.	OAT-SXCZ00	Chassis Number	PN1BA3CD306149778
Engine Size	2755 cc	Transmission	Automatic
Mileage	500 km	Registration Date	2026-06-18
Make and Model	TOYOTA HILUX HILUX DOUBLE CAB 2.8 AT 4X4	Exterior Colour	BLACK
Propellant	PETROL / GASOLINE	Seats	5
Dimensions	5.32 × 1.90 m		


STANDARD FEATURES

✓ Power Steering	✓ Power Seat	✓ Power Windows
✓ Power Mirrors	✓ Keyless Entry	✓ Push Start
✓ Driver Airbag	✓ Passenger Airbag	✓ Leather Seats
✓ Back Camera	✓ Fog Lights	✓ 360-Degree Camera
✓ Alloy Wheels	✓ AM/FM Radio	✓ Central Locking System
✓ Air Conditioning	✓ 4WD	

SUPPLIER'S CONDITION REPORT

Corrosion	No	Yes	
Under Body Holes	No	Yes	
Under Body Broken	No	Yes	
Engine	Working 	Not Working	None
Brake System	Working 	Not Working	None
Power Window	Working	Not Working 	None
Transmission	Working 	Not Working	None
A/C	Working 	Not Working	None
Audio System	Working 	Not Working	None
4WD	Working 	Not Working	None

BODY CONDITION



BODY CONDITION DETAILS

No body-condition defects have been recorded for this vehicle.

Date: 9/9/2026

Optimus Auto Trading Group

This report is generated for internal use and customer reference. All information is accurate as of the date of inspection. Any subsequent alterations, adjustments or events are not covered in this evaluation.