

Vehicle Inspection Report

Stock No.: OAT-MYFBXG

VEHICLE SPECIFICATIONS

Stock No.	OAT-MYFBXG	Chassis Number	FB70BBA10806
Engine Size	2977 cc	Transmission	MANUAL
Mileage	100,500 km	Registration Date	2009-04-13
Make and Model	MITSUBISHI CANTER GUTS FB70BR1SRDEA	Exterior Colour	WHITE
Propellant	PETROL / GASOLINE	Seats	2
Dimensions	4.72 × 1.72 m		


STANDARD FEATURES

✓ AM/FM Radio	✓ Air Conditioning	✓ Central Locking System
✓ Non-Smoker	✓ Power Steering	✓ Power Windows

SUPPLIER'S CONDITION REPORT

Corrosion		Yes	
Under Body Holes		Yes	
Under Body Broken		Yes	
Engine	Working 	Not Working	None
Brake System	Working 	Not Working	None
Power Window	Working 	Not Working	None
Transmission	Working 	Not Working	None
A/C	Working 	Not Working	None
Audio System	Working 	Not Working	None
4WD	Working	Not Working	None 

BODY CONDITION



LEGEND

- A** Minor Dent
Approx. 20-cent coin size
- B** Major Dent
Approx. \$1 coin size

BODY CONDITION DETAILS

No.	Defect	Information Details
F1	Chip	Paint Chip (Right side mirror)
F2	Other	Scratch (Left side door)
F3	Other	Scratch (Left side panel)

Date: 9/30/2026

Optimus Auto Trading Group

This report is generated for internal use and customer reference. All information is accurate as of the date of inspection. Any subsequent alterations, adjustments or events are not covered in this evaluation.