

Vehicle Inspection Report

Stock No.: OAT-H6LZMN

VEHICLE SPECIFICATIONS

Stock No.	OAT-H6LZMN	Chassis Number	MRHRM3850HP000037
Engine Size	2354 cc	Transmission	Automatic
Mileage	59,000 km	Registration Date	2016-03-31
Make and Model	HONDA CRV 2.4 5AT S/R REVCAM	Exterior Colour	WHITE
Propellant	PETROL / GASOLINE	Seats	5
Dimensions	4.53 × 1.82 m		


STANDARD FEATURES

✓ Push Start	✓ Driver Airbag	✓ Power Steering
✓ Power Mirrors	✓ Leather Seats	✓ Power Seat
✓ Passenger Airbag	✓ Power Windows	✓ Side Airbags
✓ Keyless Entry	✓ Back Camera	✓ Alloy Wheels
✓ Fog Lights	✓ CD Player	✓ AM/FM Radio
✓ Antilock Braking System (ABS)	✓ Central Locking System	✓ Electronic Stability Control (ESC)
✓ Sunroof	✓ Non-Smoker	

SUPPLIER'S CONDITION REPORT

Corrosion	No	Yes	
Under Body Holes	No	Yes	
Under Body Broken	No	Yes	
Engine	Working	Not Working	None
Brake System	Working	Not Working	None
Power Window	Working	Not Working	None
Transmission	Working	Not Working	None
A/C	Working	Not Working	None
Audio System	Working	Not Working	None
4WD	Working	Not Working	None

BODY CONDITION



BODY CONDITION DETAILS

No body-condition defects have been recorded for this vehicle.

Date: 9/10/2026

Optimus Auto Trading Group

This report is generated for internal use and customer reference. All information is accurate as of the date of inspection. Any subsequent alterations, adjustments or events are not covered in this evaluation.