

Vehicle Inspection Report

Stock No.: OAT-4BXPJP

VEHICLE SPECIFICATIONS

Stock No.	OAT-4BXPJP	Chassis Number	MR053REH104554553
Engine Size	1596 cc	Transmission	Automatic
Mileage	68,400 km	Registration Date	2016-11-16
Make and Model	TOYOTA COROLLA ALTIS COROLLA ALTIS 1.6 CVT	Exterior Colour	BROWN
Propellant	PETROL / GASOLINE	Seats	5
Dimensions	4.64 × 1.78 m		


STANDARD FEATURES

✓ Keyless Entry	✓ Passenger Airbag	✓ Power Windows
✓ Power Seat	✓ Back Camera	✓ Alloy Wheels
✓ AM/FM Radio	✓ Antilock Braking System (ABS)	✓ Air Conditioning
✓ Non-Smoker	✓ Central Locking System	✓ Electronic Stability Control (ESC)
✓ Fog Lights	✓ Leather Seats	✓ Power Mirrors
✓ Power Steering	✓ Driver Airbag	✓ Push Start

SUPPLIER'S CONDITION REPORT

Corrosion	No	Yes	
Under Body Holes	No	Yes	
Under Body Broken	No	Yes	
Engine	Working	Not Working	None
Brake System	Working	Not Working	None
Power Window	Working	Not Working	None
Transmission	Working	Not Working	None
A/C	Working	Not Working	None
Audio System	Working	Not Working	None
4WD	Working	Not Working	None

BODY CONDITION



LEGEND

- A** Minor Dent
Approx. 20-cent coin size
- B** Major Dent
Approx. \$1 coin size

BODY CONDITION DETAILS

No.	Defect	Information Details
F1	Other	Minor scratch (Rear right bumper)

Date: 9/25/2026

Optimus Auto Trading Group

This report is generated for internal use and customer reference. All information is accurate as of the date of inspection. Any subsequent alterations, adjustments or events are not covered in this evaluation.