

Vehicle Inspection Report

Stock No.: OAT-8GU2BQ

VEHICLE SPECIFICATIONS

Stock No.	OAT-8GU2BQ	Chassis Number	WBAWY920700R99721
Engine Size	1997 cc	Transmission	Automatic
Mileage	52,900 km	Registration Date	2016-07-21
Make and Model	BMW X3 SDRIVE 20I HID	Exterior Colour	SILVER
Propellant	PETROL / GASOLINE	Seats	5
Dimensions	4.66 × 1.88 m		


STANDARD FEATURES

✓ Push Start	✓ Driver Airbag	✓ Power Steering
✓ Power Mirrors	✓ Leather Seats	✓ Navigation
✓ Fog Lights	✓ Central Locking System	✓ Electronic Stability Control (ESC)
✓ Non-Smoker	✓ Wheel Spanner	✓ Jack
✓ Sunroof	✓ Air Conditioning	✓ Antilock Braking System (ABS)
✓ AM/FM Radio	✓ Alloy Wheels	✓ Parking Sensors
✓ Back Camera	✓ Power Seat	✓ Power Windows
✓ Passenger Airbag	✓ Keyless Entry	

SUPPLIER'S CONDITION REPORT

Corrosion	No	Yes	
Under Body Holes	No	Yes	
Under Body Broken	No	Yes	
Engine	Working	Not Working	None
Brake System	Working	Not Working	None
Power Window	Working	Not Working	None
Transmission	Working	Not Working	None
A/C	Working	Not Working	None
Audio System	Working	Not Working	None
4WD	Working	Not Working	None

BODY CONDITION



LEGEND

- A** Minor Dent
Approx. 20-cent coin size
- B** Major Dent
Approx. \$1 coin size

BODY CONDITION DETAILS

No body-condition defects have been recorded for this vehicle.

Date: 9/22/2026

Optimus Auto Trading Group

This report is generated for internal use and customer reference. All information is accurate as of the date of inspection. Any subsequent alterations, adjustments or events are not covered in this evaluation.