

Vehicle Inspection Report


Stock No.: OAT-6Y67B6

VEHICLE SPECIFICATIONS			
Stock No.	OAT-6Y67B6	Chassis Number	JM6GJ1072G0242907
Engine Size	1998 cc	Transmission	Automatic
Mileage	58,700 km	Registration Date	2016-09-23
Make and Model	MAZDA MAZDA6 4-DOOR SEDAN 2.0L SP6FAT	Exterior Colour	GRAY / GREY
Propellant	PETROL / GASOLINE	Seats	5
Dimensions	4.87 × 1.84 m		

STANDARD FEATURES		
✓ Keyless Entry	✓ Passenger Airbag	✓ Power Windows
✓ Back Camera	✓ Alloy Wheels	✓ AM/FM Radio
✓ Antilock Braking System (ABS)	✓ Air Conditioning	✓ Non-Smoker
✓ Electronic Stability Control (ESC)	✓ Central Locking System	✓ Fog Lights
✓ Leather Seats	✓ Power Mirrors	✓ Power Steering
✓ Driver Airbag	✓ Push Start	

SUPPLIER'S CONDITION REPORT			
Corrosion	No	Yes	
Under Body Holes	No	Yes	
Under Body Broken	No	Yes	
Engine	Working	Not Working	None
Brake System	Working	Not Working	None
Power Window	Working	Not Working	None
Transmission	Working	Not Working	None
A/C	Working	Not Working	None
Audio System	Working	Not Working	None
4WD	Working	Not Working	None

BODY CONDITION



LEGEND

- A** Minor Dent
Approx. 20-cent coin size
- B** Major Dent
Approx. \$1 coin size

BODY CONDITION DETAILS

No.	Defect	Information Details
F1	Other	Minor scratch (Rear right fender)

Date: 9/25/2026

Optimus Auto Trading Group

This report is generated for internal use and customer reference. All information is accurate as of the date of inspection. Any subsequent alterations, adjustments or events are not covered in this evaluation.