OPTIMUS AUTO TRADING GROUP

REPORT DATE
Tue Sep 22 2026
REPORT VERSION: 9

Vehicle Inspection Report

Stock No.: OAT-SXCZ00

VEHICLE SPECIFICATIONS

Stock No.	OAT-SXCZ00	**Chassis Number**	PN1BA3CD306149778
Engine Size	2755 cc	**Transmission**	Automatic
Mileage	500 km	**Registration Date**	2026-06-18
Make and Model	TOYOTA HILUX HILUX DOUBLE CAB 2.8 AT 4X4	**Exterior Colour**	BLACK
Propellant	PETROL / GASOLINE	**Seats**	5
Dimensions	5.32 × 1.90 m		


STANDARD FEATURES

✓ Power Steering	✓ Power Seat	✓ Power Windows
✓ Power Mirrors	✓ Keyless Entry	✓ Push Start
✓ Driver Airbag	✓ Passenger Airbag	✓ Leather Seats
✓ Back Camera	✓ Fog Lights	✓ 360-Degree Camera
✓ Alloy Wheels	✓ AM/FM Radio	✓ Central Locking System
✓ Air Conditioning	✓ 4WD	

SUPPLIER'S CONDITION REPORT

Corrosion	✓ No	Yes	
Under Body Holes	✓ No	Yes	
Under Body Broken	✓ No	Yes	
Engine	✓ Working	Not Working	None
Brake System	✓ Working	Not Working	None
Power Window	✓ Working	Not Working	None
Transmission	✓ Working	Not Working	None
A/C	✓ Working	Not Working	None
Audio System	✓ Working	Not Working	None
4WD	✓ Working	Not Working	None

BODY CONDITION



LEGEND

A	**Minor Dent** Approx. 20-cent coin size
B	**Major Dent** Approx. $1 coin size

BODY CONDITION DETAILS

No body-condition defects have been recorded for this vehicle.

Date: 9/22/2026

This report is generated for internal use and customer reference. All information is accurate as of the date of inspection. Any subsequent alterations, adjustments or events are not covered in this evaluation.