

## Vehicle Inspection Report

Stock No.: OAT-C5928K

### VEHICLE SPECIFICATIONS

|                |                               |                   |                   |
|----------------|-------------------------------|-------------------|-------------------|
| Stock No.      | OAT-C5928K                    | Chassis Number    | MR2BE3BE200035717 |
| Engine Size    | 1598 cc                       | Transmission      | Automatic         |
| Mileage        | 10 km                         | Registration Date | 2026              |
| Make and Model | TOYOTA COROLLA ALTIS STANDARD | Exterior Colour   | WHITE             |
| Propellant     | PETROL / GASOLINE             | Seats             | 5                 |
| Dimensions     | 4.63 × 1.78 m                 |                   |                   |


### STANDARD FEATURES

|                                 |                                      |                          |
|---------------------------------|--------------------------------------|--------------------------|
| ✓ Keyless Entry                 | ✓ Passenger Airbag                   | ✓ Power Windows          |
| ✓ Power Seat                    | ✓ Push Start                         | ✓ Power Steering         |
| ✓ Driver Airbag                 | ✓ Power Mirrors                      | ✓ Alloy Wheels           |
| ✓ Antilock Braking System (ABS) | ✓ Electronic Stability Control (ESC) | ✓ Central Locking System |
| ✓ Non-Smoker                    |                                      |                          |

### SUPPLIER'S CONDITION REPORT

|                   |               |             |                 |
|-------------------|---------------|-------------|-----------------|
| Corrosion         | <del>No</del> | Yes         |                 |
| Under Body Holes  | <del>No</del> | Yes         |                 |
| Under Body Broken | <del>No</del> | Yes         |                 |
| Engine            | Working       | Not Working | None            |
| Brake System      | Working       | Not Working | None            |
| Power Window      | Working       | Not Working | None            |
| Transmission      | Working       | Not Working | None            |
| A/C               | Working       | Not Working | None            |
| Audio System      | Working       | Not Working | None            |
| 4WD               | Working       | Not Working | <del>None</del> |

BODY CONDITION



LEGEND

- A** Minor Dent  
Approx. 20-cent coin size
- B** Major Dent  
Approx. \$1 coin size

BODY CONDITION DETAILS

No body-condition defects have been recorded for this vehicle.

Date: 9/24/2026

---

**Optimus Auto Trading Group**

This report is generated for internal use and customer reference. All information is accurate as of the date of inspection. Any subsequent alterations, adjustments or events are not covered in this evaluation.