OPTIMUS AUTO TRADING GROUP

REPORT DATE
Wed Nov 18 2026
REPORT VERSION: 2

Vehicle Inspection Report

Stock No.: OAT-FD21L3

VEHICLE SPECIFICATIONS

Stock No.	OAT-FD21L3	**Chassis Number**	WBAHS120X05H48063
Engine Size	1499 cc	**Transmission**	Automatic
Mileage	777,100 km	**Registration Date**	2017-06-28
Make and Model	BMW X1 SDRIVE18I AT LED NAV	**Exterior Colour**	BROWN
Propellant	PETROL / GASOLINE	**Seats**	5
Dimensions	4.45 × 1.82 m		


STANDARD FEATURES

✓ Keyless Entry	✓ Passenger Airbag	✓ Power Windows
✓ Power Seat	✓ Back Camera	✓ Alloy Wheels
✓ Parking Sensors	✓ CD Player	✓ AM/FM Radio
✓ Antilock Braking System (ABS)	✓ Air Conditioning	✓ Non-Smoker
✓ Electronic Stability Control (ESC)	✓ Central Locking System	✓ Fog Lights
✓ Navigation	✓ 360-Degree Camera	✓ Power Mirrors
✓ Leather Seats	✓ Power Steering	✓ Driver Airbag
✓ Push Start		

SUPPLIER'S CONDITION REPORT

Corrosion	✓ No	Yes	
Under Body Holes	✓ No	Yes	
Under Body Broken	✓ No	Yes	
Engine	✓ Working	Not Working	None
Brake System	✓ Working	Not Working	None
Power Window	✓ Working	Not Working	None
Transmission	✓ Working	Not Working	None
A/C	✓ Working	Not Working	None
Audio System	✓ Working	Not Working	None
4WD	Working	Not Working	✓ None

BODY CONDITION



LEGEND

A	**Minor Dent** Approx. 20-cent coin size
B	**Major Dent** Approx. $1 coin size

BODY CONDITION DETAILS

No.	Defect	Information Details
F1	Other	Minor scratch (Right front bumper)

Date: 11/18/2026

This report is generated for internal use and customer reference. All information is accurate as of the date of inspection. Any subsequent alterations, adjustments or events are not covered in this evaluation.