

Vehicle Inspection Report

Stock No.: OAT-6DFNCU

VEHICLE SPECIFICATIONS

Stock No.	OAT-6DFNCU	Chassis Number	RC11117355
Engine Size	2356 cc	Transmission	Automatic
Mileage	67,200 km	Registration Date	2016-09-09
Make and Model	HONDA ODYSSEY ABSOLUTE 2.4 CVT ABS AIRBAG 2WD	Exterior Colour	MAROON
Propellant	PETROL / GASOLINE	Seats	7
Dimensions	4.83 × 1.82 m		


STANDARD FEATURES

✓ Keyless Entry	✓ Passenger Airbag	✓ Power Windows
✓ Back Camera	✓ Alloy Wheels	✓ AM/FM Radio
✓ Antilock Braking System (ABS)	✓ Air Conditioning	✓ Non-Smoker
✓ Electronic Stability Control (ESC)	✓ Central Locking System	✓ Leather Seats
✓ Power Mirrors	✓ Power Steering	✓ Driver Airbag
✓ Push Start		

SUPPLIER'S CONDITION REPORT

Corrosion	No	Yes	
Under Body Holes	No	Yes	
Under Body Broken	No	Yes	
Engine	Working Working	Not Working	None
Brake System	Working Working	Not Working	None
Power Window	Working Working	Not Working	None
Transmission	Working Working	Not Working	None
A/C	Working Working	Not Working	None
Audio System	Working Working	Not Working	None
4WD	Working	Not Working	None

BODY CONDITION



BODY CONDITION DETAILS

No.	Defect	Information Details
F1	Other	MINOR SCRATCH (REAR BUMPER)

Date: 9/12/2026

Optimus Auto Trading Group

This report is generated for internal use and customer reference. All information is accurate as of the date of inspection. Any subsequent alterations, adjustments or events are not covered in this evaluation.