OPTIMUS AUTO TRADING GROUP

REPORT DATE
Tue Nov 24 2026
REPORT VERSION: 4

Vehicle Inspection Report

Stock No.: OAT-NBYLZL

VEHICLE SPECIFICATIONS

Stock No.	OAT-NBYLZL	**Chassis Number**	JHMRU1830GX200799
Engine Size	1496 cc	**Transmission**	Automatic
Mileage	74,700 km	**Registration Date**	2016-11-21
Make and Model	HONDA HR-V 1.5 LX CVT REVCAM	**Exterior Colour**	WHITE
Propellant	PETROL / GASOLINE	**Seats**	5
Dimensions	4.29 × 1.77 m		


STANDARD FEATURES

✓ Keyless Entry	✓ Passenger Airbag	✓ Power Windows
✓ Back Camera	✓ Alloy Wheels	✓ AM/FM Radio
✓ Antilock Braking System (ABS)	✓ Air Conditioning	✓ Non-Smoker
✓ Electronic Stability Control (ESC)	✓ Central Locking System	✓ Fog Lights
✓ Leather Seats	✓ Push Start	✓ Driver Airbag
✓ Power Steering	✓ Power Mirrors	

SUPPLIER'S CONDITION REPORT

Corrosion	✓ No	Yes	
Under Body Holes	✓ No	Yes	
Under Body Broken	✓ No	Yes	
Engine	✓ Working	Not Working	None
Brake System	✓ Working	Not Working	None
Power Window	✓ Working	Not Working	None
Transmission	✓ Working	Not Working	None
A/C	✓ Working	Not Working	None
Audio System	✓ Working	Not Working	None
4WD	Working	Not Working	✓ None

BODY CONDITION



LEGEND

A	**Minor Dent** Approx. 20-cent coin size
B	**Major Dent** Approx. $1 coin size

BODY CONDITION DETAILS

No.	Defect	Information Details
F1	Chip	Paint chip (Left front fender)

Date: 11/24/2026

This report is generated for internal use and customer reference. All information is accurate as of the date of inspection. Any subsequent alterations, adjustments or events are not covered in this evaluation.