OPTIMUS AUTO TRADING GROUP

REPORT DATE
Fri Nov 06 2026
REPORT VERSION: 6

Vehicle Inspection Report

Stock No.: OAT-JRNDA4

VEHICLE SPECIFICATIONS

Stock No.	OAT-JRNDA4	**Chassis Number**	WBAHS720805E80973
Engine Size	1998 cc	**Transmission**	Automatic
Mileage	54,300 km	**Registration Date**	2016-11-04
Make and Model	BMW X1 SDRIVE20I LED NAV HUD SR	**Exterior Colour**	GRAY / GREY
Propellant	PETROL / GASOLINE	**Seats**	5
Dimensions	4.45 × 1.82 m		


STANDARD FEATURES

✓ Keyless Entry	✓ Passenger Airbag	✓ Power Windows
✓ Power Seat	✓ Back Camera	✓ Alloy Wheels
✓ Parking Sensors	✓ AM/FM Radio	✓ Antilock Braking System (ABS)
✓ Air Conditioning	✓ Sunroof	✓ Non-Smoker
✓ Electronic Stability Control (ESC)	✓ Central Locking System	✓ Fog Lights
✓ Navigation	✓ Leather Seats	✓ Power Mirrors
✓ Power Steering	✓ Driver Airbag	✓ Push Start

SUPPLIER'S CONDITION REPORT

Corrosion	No ✓	Yes	
Under Body Holes	No ✓	Yes	
Under Body Broken	No ✓	Yes	
Engine	Working ✓	Not Working	None
Brake System	Working ✓	Not Working	None
Power Window	Working ✓	Not Working	None
Transmission	Working ✓	Not Working	None
A/C	Working ✓	Not Working	None
Audio System	Working ✓	Not Working	None
4WD	Working	Not Working	None ✓

BODY CONDITION



LEGEND

A	**Minor Dent** Approx. 20-cent coin size
B	**Major Dent** Approx. $1 coin size

BODY CONDITION DETAILS

No.	Defect	Information Details
F1	Other	Minor scratch (Left front fender)

Date: 11/6/2026

This report is generated for internal use and customer reference. All information is accurate as of the date of inspection. Any subsequent alterations, adjustments or events are not covered in this evaluation.