OPTIMUS AUTO TRADING GROUP

REPORT DATE
Wed Oct 14 2026
REPORT VERSION: 4

Vehicle Inspection Report

Stock No.: OAT-MGRBHU

VEHICLE SPECIFICATIONS

Stock No.	OAT-MGRBHU	**Chassis Number**	WBAHS720305E81125
Engine Size	1998 cc	**Transmission**	Automatic
Mileage	64,900 km	**Registration Date**	2016-10-13
Make and Model	BMW X1 SDRIVE20I LED NAV	**Exterior Colour**	BLACK
Propellant	PETROL / GASOLINE	**Seats**	5
Dimensions	4.45 × 1.82 m		


STANDARD FEATURES

✓ Keyless Entry	✓ Passenger Airbag	✓ Power Windows
✓ Power Seat	✓ Back Camera	✓ Alloy Wheels
✓ AM/FM Radio	✓ Antilock Braking System (ABS)	✓ Air Conditioning
✓ Non-Smoker	✓ Electronic Stability Control (ESC)	✓ Central Locking System
✓ Navigation	✓ Push Start	✓ Power Steering
✓ Power Mirrors	✓ Driver Airbag	✓ Leather Seats
✓ Fog Lights		

SUPPLIER'S CONDITION REPORT

Corrosion	No ✓	Yes	
Under Body Holes	No ✓	Yes	
Under Body Broken	No ✓	Yes	
Engine	Working ✓	Not Working	None
Brake System	Working ✓	Not Working	None
Power Window	Working ✓	Not Working	None
Transmission	Working ✓	Not Working	None
A/C	Working ✓	Not Working	None
Audio System	Working ✓	Not Working	None
4WD	Working	Not Working	None ✓

BODY CONDITION



LEGEND

A	**Minor Dent** Approx. 20-cent coin size
B	**Major Dent** Approx. $1 coin size

BODY CONDITION DETAILS

No body-condition defects have been recorded for this vehicle.

Date: 10/14/2026

This report is generated for internal use and customer reference. All information is accurate as of the date of inspection. Any subsequent alterations, adjustments or events are not covered in this evaluation.